

# Fusing Farm Fine Frit

Fusing Farm  
Fine Frit  
Tack- Fuse -  
Full Melt  
in °Fahrenheit

1015°

1185°

1295°

1353°

1380°

1370°

1320°

1218°

1089°

941°

FINE

