

Fusing Farm
Medium Frit
Tack- Fuse -
Full Melt
in °Farenheit

Fusing Farm Medium Frit

- 946°
- 1075°
- 1242°
- 1340°
- 1393°
- 1410°
- 1400°
- 1356°
- 1258°
- 1118°
- 980°

MEV

